

Manhole Inspection Summary

Manhole # S13CC_024MH

Printed On: 6/25/2009

Page 1 of 3

Inspection ☒ **Is Incomplete** Rating:

Record Plat: **13CC** Node: **024** Status: **Not Found**

Insp Date: **1/12/09 10:53 AM**

Incomplete Comments

Cannot Access - Buried - Manhole Existing Confirmed by As-built

Crew: **ADS4**
Inspector: **ADS1**
Firm: **ADS**

Location Address: **1104 DUKELAND ST**

Cross Street: **RIGGS AVE**

Manhole Type: Location: Ground Conditions:

☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **BELIEVE IT IS A GAS FEATURE IN THE STREET**

Cover Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)

Type: **Sanitary** Condition: Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

Frame Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

Chimney / Frame Adjustment ☐ Exists Material: ☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Corbel Material: ☐ Parged Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Barrel Material: ☐ Parged

Shape: Diameter: (in.) Length: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

Bench ☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Channel Material: ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

Steps Count: Missing: ☐ Corroded

Surcharge ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

Manhole Inspection Summary

Manhole # S13CC_024MH

Printed On: 6/25/2009

Page 2 of 3

Location View



Top View



